

Lateral "I" Patella Stabilizer


Warnings and Instructions: Review carefully, proper application is required


Warning: This device will not prevent or eliminate risk of injury. Do Not Over-tighten. If swelling, pain, skin irritation, or an unusual reaction occurs, discontinue use immediately and consult your medical professional. This device should not be worn by persons with known allergies to neoprene.

Care: Hand wash using mild soap. Rinse thoroughly. Air dry only. Do not tumble dry.











1185 East Main St., Santa Paula, California 93060 California: 800-221-5465, National: 800-654-3241 International: 805-525-4244, fax:805-933-2348 U.S. fax: 800-559-5975, www.hely-weber.com

EC REP MDSS GmbH, Schiffgraben 41 30175 Hannover, Germany


Rev A 2/09


Lateral "I" Patella Stabilizer


Warnings and Instructions: Review carefully, proper application is required


Warning: This device will not prevent or eliminate risk of injury. Do Not Over-tighten. If swelling, pain, skin irritation, or an unusual reaction occurs, discontinue use immediately and consult your medical professional. This device should not be worn by persons with known allergies to neoprene.

Care: Hand wash using mild soap. Rinse thoroughly. Air dry only. Do not tumble dry.











© 2009 Weber Orthopedic Inc. DBA Hely & Weber All rights reserved.

1185 East Main St., Santa Paula, California 93060 California: 800-221-5465, National: 800-654-3241 International: 805-525-4244, fax:805-933-2348 U.S. fax: 800-559-5975, www.hely-weber.com

MDSS GmbH, Schiffgraben 41 30175 Hannover, Germany

Rev A